

Annual Air Quality Index of Different monitored Stations in Odisha for the year, 2018

Monitoring Locations	Sub index value w.r.t parameter							Overall AQI of the area w.r.t parameter	Overall Categorisation
	PM ₁₀	PM _{2.5}	SO ₂	NO ₂	NH ₃	O ₃	Pb		
1.Angul									
1.Industrial Estate	100.0	82.0	12.0	32.0	-	-		100.0 (PM₁₀)	Satisfactory
2.NALCO Nagar									
2.Talcher									
3.TTPS , Talcher	106.0	83.0	12.0	35.0	-	-	-	106.0 (PM₁₀)	Moderate
4.MCL, Talcher									
3.Balasore									
5.R.O, SPCB Sahadevkhunta	86.0	78.0	3.0	14.0	-	-		86.0 (PM₁₀)	Satisfactory
6.DIC office, Angaragadia									
7.Rasalpur,I.E									
4.Berhampur									
8.R.O, SPCB Brahamanagar	64.0	55.0	3.0	24.0	-	-	-	64.0 (PM₁₀)	Satisfactory
5.Bhubaneswar									
9.SPCB Office Building, Unit-VIII	94.0	52.0	3.0	21.0	12.0	23.0	1.8	94.0 (PM₁₀)	Satisfactory
10.I.R.C. Village, Nayapalli									
11.Capital Police Station, Unit-I									
12.Chandrasek-harpur									
13.Patrapada									
14.Palasuni water works									
6.Bonaigarh									
15.Bonai Govt. Hospital	99.0	60.0	11.0	15.0	-	-	-	99.0 (PM₁₀)	Satisfactory
7.Cuttack									
16.Traffic Tower Badambadi,	109.0	80.0	3.0	39.0	-	-	-	109.0 (PM₁₀)	Moderate
17.R.O.Building, Surya Vihar									
18.PHD office ,Barabati									
8.Jharsuguda									
19.RO Building,Cox Colony, Babubagicha,	104.0	93.0	10.0	20.0	-	-	-	104.0 (PM₁₀)	Moderate
20. Inside TRL Colony Premises									
9.Kalinganagar									
21.Over the roof of TATA Guest House	122.0	98.0	3.0	13.0	-	-	-	122.0 (PM₁₀)	Moderate
22.Roof of Regional Office Building,									

Annual Air Quality Index of Different monitored Stations in Odisha for the year, 2018

Monitoring Locations	Sub index value w.r.t parameter							Overall AQI of the area w.r.t parameter	Overall Categorisation
	PM ₁₀	PM _{2.5}	SO ₂	NO ₂	NH ₃	O ₃	Pb		
10.Keonjhar									
23.R.O, Baniapat	106.0	82.0	3.0	17.0	-	-	-	106.0 (PM₁₀)	Moderate
11.Konark									
24.Konark Police Station	80.0	NM	3.0	15.0	12.0	22.0	1.3	80.0 (PM₁₀)	Satisfactory
12.Paradeep									
25.PPL Guest House	113.0	80.0	23.0	14.0	-	-	-	113.0 (PM₁₀)	Moderate
26.On the roof of IFFCO STP									
27.On the roof of Paradeep port trust									
13.Puri									
28. Sadar police Station	88.0	NM	3.0	18.0	13.0	23.0	1.6	88.0 (PM₁₀)	Satisfactory
29. Town police Station									
14.Rayagada									
30. RO Building, Indiranagar	63.0	66.0	3.0	23.0	-	-	-	66.0(PM_{2.5})	Satisfactory
31. LPS High School, Jaykaypur									
15.Rajgangpur									
32. DISR Rajgangpur	127.0	78.0	19.0	25.0	-	-	-	127.0 (PM₁₀)	Moderate
16.Rourkela									
33.Regional Office Building, Sector-5	106.0	77.0	11.0	18.0	-	-	-	106.0 (PM₁₀)	Moderate
34. IDL Outpost									
35. IDCO Water Tank, IDC Kalunga									
36. Kuarmunda Out Post, Kuarmunda									
17.Sambalpur									
37.PHD Office, Modipara	84.0	87.0	6.0	26.0	-	-	-	87.0 (PM_{2.5})	Satisfactory

NM-Not Monitored

AQI value with Categorisation

0-50	51-100	101-200	201-300	301-400	>400
GOOD	SATISFACTORY	MODERATE	POOR	VERY POOR	SEVERE